



INFORMATION BULLETIN

IFR 4000 INFORMATION BULLETIN NO. 23 SOFTWARE V2.19 UPDATE AND MANUAL CHANGES

I. PLANNING INFORMATION:

A. Effectivity:

IFR 4000's with software version 2.17 and lower.

B. Reasons:

Changes have been made to the IFR 4000 software and the IFR 4000 Operations and the IFR 4000 Getting Started manuals have been updated.

C. Description:

- Software change supports a new attenuator IC being installed in the RF block.
- When a Marker tone is selected in the Marker Mode, a description as to which Marker tone it is and which Marker light color in the cockpit should appear.
- Fixed a problem in Guided Test which caused it to lock up if the Step button was pressed too fast.
- Fixed a problem with the Peak Hold function not working correctly.
- Updated IFR 4000 Getting Started and IFR 4000 Operations manuals to reflect changes on Marker Mode screen.

II. CONTACT INFORMATION:

Contact Aeroflex for more information.

Customer Service Dept.
10200 W. York
Wichita, KS 67215

Telephone: (800) 835-2350
FAX: (316) 524-2623
Email: americas.service@aeroflex.com