

Software Release Notes

ALT-9000 Software Version 1.7.3 Available

10/03/2022

Description

The latest released software version for the ALT-9000 has changed from Version 1.7.1 to Version 1.7.3.

New Features

- None

Improvements

- Eliminated a 35-40 second delay (Longer with slower rates entered) from the time “running” is displayed to the time the ramp actually starts.
- Fixed an error message of “Signal at RF in appears to be CW”
- Fixed Minimum Alt bubble not displaying in FMCW, CDF and Gated FMCW.
- Removed the buffer on the RUN/STOP button.

Errata

- NA

Download Instructions

- The most current software version for the ALT-9000 is available as a download by [Clicking Here](#).

Contact Information

VIAVI Solutions
Avionics and Radio Test
10200 West York Street
Wichita, KS 67215
800-835-2350

Techsupport.avcomm@viavisolutions.com

ALT-9000 Software Version 1.7.1 Available

5/17/2022

Description

- This is the initial release of the ALT-9000 and is currently being shipped in new ALT-9000 units.

New Features

- General: Initial release

Improvements

- General: Initial release

Errata

- NA