

Software Release Notes

AVX-10K Software Version 2.0.20 Available

11/16/2021

New Features

General: None

Improvements

- General:
 - Corrected System Settings Calibration date
- Transponder Autotest:
 - Addressed lockup issue when running a transponder autotest
 - Fixed Reply Ratio failing in Mode S auto test
- TCAS:
 - Fixed the TCAS Mode S Pulse Shape
- UAT:
 - Fixed UAT Gen Latitude and Longitude discrepancy
- VSWR/DTF:
 - Added save & recall for VSWR calibration
 - Corrected some VSWR UI issues

Errata

Failures of Generic ATCRBS tests- testing of ATCRBS only transponders results in the transponder autotest fail.

This will be corrected on the next firmware release.

Download Instructions

- The most current software version for updating via USB drives for the AVX-10K is available as a download by [Clicking Here](#).
- This software version can be deployed to your AVX-10K through [your StrataSync account](#).

Contact Information

VIAVI Solutions
Avionics and Radio Test
10200 West York Street

Wichita, KS 67215

800-835-2350

Techsupport.avcomm@viavisolutions.com

AVX-10K Software Version 1.0.39 Available

09/24/2021

New Features

- General: None

Improvements

- General:
 - Fixed pulse amplitude variation measurements
 - Test reports align with only the tests run
 - Improved performance in high traffic environments
- Fixed reply jitter measurements
- Transponder Autotest:
 - Addressed occasional lockup issue when running a transponder autotest
- TCAS:
 - Fixed altitude range and rate calculations in TCAS application when converge setting is on

Errata

- None

AVX-10K Software Version 1.0.21 Available

09/08/2021

New Features

- General: Initial release

Improvements

- General: Initial release

Errata

- TCAS instrument: Using the converge setting in the on-condition results in incorrect vertical speed calculations for the scenario. Use Converge off until the anomaly is repaired.