



Keep Your Feet Safely on the Ground and Save!

Trade in your old analyzer for a full-featured CellAdvisor™



The CellAdvisor base station analyzer equipped with RFoFiber technology lets you troubleshoot and maintain RF at ground level via fiber at the base band unit (BBU).

CellAdvisor with RFoFiber (RFoCPRI and RFoOBSAI):

- Minimizes cell tower climbs and improves safety
- Minimizes the number of instruments you need
- Significantly reduces maintenance time and operational expenses

RFoFiber technology verifies control signals and extracts RF (IQ) data transmitted between the BBU and remote radio head (RRH), permitting the monitoring and analysis of the interference of mobile terminals (uplink), as well as the radio's signal analysis (downlink).

Act now, offer expires December 30, 2016!

Terms and Conditions

- Trade in and get up to \$5,000 (USD) in credit for a CellAdvisor BaseStation Analyzer (JD740 and JD780 series)
- Trade in and get up to \$1,500 (USD) in credit for a CellAdvisor Cable and Antenna Analyzer (JD720 series)
- Viavi must receive purchase orders before December 30, 2016
- Trade-in credit applies to the list price of each bundle or product unless previously approved by Viavi
- Trade-in analyzer eligibility subject to Viavi review. Acceptable analyzers include Anritsu® BTSMaster, CellMaster, SiteMaster, and SpectrumMaster, and R&S® FSH4 and FSH8.

Key Benefits

- Provides a single, portable solution for all cell site installation and maintenance
- Performs spectrum/spectrogram analysis on CPRI and OBSAI downlinks and uplinks, including PIM detection
- Includes comprehensive signal analysis of GSM/GPRS, CDMA/EV-DO, WCDMA/HSDPA, and LTE/LTE-Advanced (optional)
- Analyzes LTE multimedia broadcast multicast services (eMBMS, optional)
- Verifies coaxial and fiber fronthaul including optical power and fiber inspection (optional)
- Standard three-year warranty

Contact Us **+1 844 GO VIAVI**
(+1 844 468 4284)

To reach the Viavi office nearest you,
visit viavisolutions.com/contacts.

© 2016 Viavi Solutions Inc.
Product specifications and descriptions in this document are subject to change without notice.
rfofibercelladvisor-ps-nsd-nse-ae@viavi.com
30179591 003 1016