

FURY GPS Disciplined Oscillator

Product Replacement Information

Please be advised of the following product changes for VIAVI Fury product line.

VIAVI has transitioned legacy non-RoHS compliant Fury products to new part numbers for RoHS compliant products.

Equivalency Statement

The new RoHS Compliant Fury products are direct replacements for the legacy products in form, fit and function. This technical note serves as a letter of equivalency for the RoHS products as replacements for the non-RoHS legacy products.

Visit the [Fury web page](#) for a copy of the product data sheet.

The following table associates the legacy product part number with the replacement product part number.

RoHS Compliant Product		Legacy Product - Obsolete	
Part Number	Product Description	Part Number	Product Description
22174841	Super Fury SOCX0 OEM Board - RoHS	100028	Super Fury SOCX0 OEM Board - non-RoHS
22174842	Super Fury DOCX0 OEM Board - RoHS	100029	Super Fury DOCX0 OEM Board - non-RoHS
22174843	Super Fury SOCX0 Desktop - RoHS	100030	Super Fury SOCX0 Desktop - non-RoHS
22174844	Super Fury DOCX0 Desktop - RoHS	100031	Super Fury DOCX0 Desktop - non-RoHS

Contact Us: +1 800 835 2352 | avcomm.sales@viavisolutions.com.

© 2026 VIAVI Solutions Inc. Product specifications and descriptions in this document are subject to change without notice. Patented as described at viavisolutions.com/patents

fury-gps-dis-osc-prod-replace-info-tn-avi-nse-ae
30194871 900 0126