








Fiber Cleaning Tips and Adapters








VIAVI Solutions offers a wide variety of tips, adapters and guides for cleaning fiber connector end-faces. Browse through this comprehensive guide to determine what you need.

The FCLT Series cleaning tips attach to the **CleanBlastPRO™** and legacy **CleanBlast™** systems. FCLT tips can support both PC/UPC and APC polish types with the same tip. Some of the tips are also used in conjunction with a guide, as shown in the images below.

Catalog Part Number	Type	Product Image	Description
FCLT-U12	Universal		CleanBlast Tip for 1.25mm Bulkheads (LC, MU)
FCLT-U12-MA	Universal		CleanBlast Adapter for 1.25mm Patch Cords (LC, MU) <i>Note: Requires FCLT-U12</i>
FCLT-U12X	Universal		CleanBlast Tip for 1.25mm Bulkheads (LC, MU), Hardened Stainless Steel
FCLT-U25	Universal		CleanBlast Tip for 2.5mm Bulkheads (FC, SC, ST)
FCLT-U25-A6	Universal		CleanBlast Tip for 2.5mm Bulkheads (FC, SC, ST), Angled 60 Degrees
FCLT-U25-MA	Universal		CleanBlast Adapter for 2.5mm Patch Cords (FC, SC, ST) <i>Note: Requires FCLT-U25</i>
FCLT-SC-250	SC		CleanBlast Tip for SC Bulkheads

Catalog Part Number	Type	Product Image	Description
FCLT-SC-A6	SC		CleanBlast Tip for SC Bulkheads, Angled 60 Degrees
FCLT-SCX	SC		CleanBlast Tip for SC Bulkheads, Hardened Stainless Steel
FCLT-E2-250	E2000		CleanBlast Tip for E2000 Bulkheads
FCLT-FC-250	FC		CleanBlast Tip for FC Bulkheads
FCLT-LC	LC		CleanBlast Tip for LC Bulkheads
FCLT-LC-A6	LC		CleanBlast Tip for LC Bulkheads, Angled 60 Degrees
FCLT-MU	MU		CleanBlast Tip for MU Bulkheads
FCLT-MPX	Ribbon		CleanBlast Tip for MPX Bulkheads
FCLT-MT	Ribbon		CleanBlast Tip for MT Ferrule Bulkheads (unconnectorized)
FCLT-MTP	Ribbon		CleanBlast Tip for MPO Bulkheads
FCLT-MT-MA	Ribbon		CleanBlast Adapter for MT Ferrule (unconnectorized) <i>Note: Requires FCLT-MTP</i>
FCLT-MTP-A6	Ribbon		CleanBlast Tip for MPO Bulkheads, Angled 60 Degrees

Catalog Part Number	Type	Product Image	Description
FCLT-MTP-MA	Ribbon		CleanBlast Adapter for MPO Patch Cords <i>Note: Requires FCLT-MTP</i>
FCLT-HMFOC-P	Ribbon		CleanBlast Tip for HMFOC Drop Terminal Ports (Plug)
FCLT-HMFOC-R	Ribbon		CleanBlast Tip for HMFOC Drop Terminal Ports (Receptacle)
FCLT-EXBEAM-1	Other		CleanBlast Tip for FibrecaST Jr/Sr Expanded Beam
FCLT-SMA	Other		CleanBlast Tip for SMA Bulkheads
FCLT-BAP3-125	Mil/Aero		CleanBlast Tip for BAP3 Guides
FCLT-BAP4-125	Mil/Aero		CleanBlast Tip for BAP4 Guides
FCLT-C130	Mil/Aero		CleanBlast Tip for C130
FCLT-MIL1	Mil/Aero		CleanBlast Tip for 29504/14 and 29504/15 Termini <i>Note: Cleans Both Pins and Sockets</i>
FCLT-MIL2	Mil/Aero		CleanBlast Tip for 29504/4 and 29504/5 Termini <i>Note: Cleans Both Pins and Sockets</i>

Catalog Part Number	Type	Product Image	Description
FCLT-MIL2-A6	Mil/Aero		CleanBlast Tip for 29504/4 and 29504/5 Termini, Angled 60 Degrees <i>Note: Cleans Both Pins and Sockets</i>
FCLT-MIL2-CPA	Mil/Aero		CleanBlast Tip for Use with Glenair Test Probe Adapter
FCLT-MIL3	Mil/Aero		CleanBlast Tip for 1.25mm LuxCis Termini <i>Note: Cleans Both Pins and Sockets</i>
FCLT-MT999	Mil/Aero		CleanBlast Tip for 38999 with MT Ferrules <i>Note: Requires FBPT-MT999 Guides</i>
FCLT-RQX8-P	Mil/Aero		CleanBlast Tip for Radiall Quadrax Size 8 - Pin Side
FCLT-RQX8-S	Mil/Aero		CleanBlast Tip for Radiall Quadrax Size 8 - Socket Side
FCLT-TFOCA2	Mil/Aero		CleanBlast Tip for TFOCA-II Connectors (includes Guide)

VIAVI Solutions also offers a wide variety of fiber inspection microscopes, tips and adapters to help you Inspect Before You Connect™ and work clean.

- Learn more about fiber inspection at www.viavisolutions.com/inspect
- View a [comprehensive selection guide of inspection tips and adapters](#)
- Order what you need: Visit: www.viavisolutions.com or call 1-844-Go VIAVI (+1-844-468-4284).