

**Do these OTU8K units below
have the B43 revision to be
able to control the new E9H-
X36LCAPC (UOS) switch?**



UOS possible only for otu8kv2 with hardware card B43 rev >= 6


Please, check SCPI:

OTU:EEXTERNAL:VERSION:HARD?

How to check using below procedure.

Answer:

All are v6 and above. See below.



For any other technical information inquiries, please contact us at tac.apac@viavisolutions.com